



Sample Program Approval Listing Shot Peening

喷丸样品批准清单

桨叶表面喷丸

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
Runway Aviation Goias	Not Approved	Not Approved	11/30/26	Not Approved	Not Approved
Serrana Aircraft Maintenance Sao Gabriel	Not Approved	Not Approved	10/31/26	Not Approved	Not Approved
Canada					
<i>Canadian Propeller Winnipeg</i> <i>Manitoba</i>	<i>9/30/26</i>	<i>*1/31/27</i>	<i>9/30/26</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Hope Aero Propeller and Components Inc.</i> <i>Mississauga</i> <i>Ontario</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>3/31/26</i>	<i>12/31/24</i>	<i>Not Approved</i>
Propworks Propeller Systems Inc. Edmonton Alberta	8/31/24	*4/30/25	12/31/25	Not Approved	Not Approved
Western Propeller Co. Ltd. Richmond British Columbia	Not Approved	*11/30/24	12/31/26	Not Approved	Not Approved
Chile					
Enaer-Empresa Nacional De Aeronautica	Not Approved	Not Approved	Not Approved	Not Approved	Not Approved
China					
Metal Improvement Suzhou Jiangsu	7/31/25	7/31/25	7/31/25	Not Approved	Not Approved
Civil Aviation Flight University of China	Not Approved	Not Approved	3/31/26	Not Approved	Not Approved

Shot Peening Approval Listing

* Approved for Steel Clamps only